

UNITED STATES PATENT AND TRADEMARK OFFICE  
**CERTIFICATE OF CORRECTION**

PATENT NO. : 7,714,633 B2  
APPLICATION NO. : 10/593577  
DATED : May 11, 2010  
INVENTOR(S) : Kiyoshi Kato et al.

Page 1 of 1

It is certified that error appears in the above-identified patent and that said Letters Patent is hereby corrected as shown below:

At column 32, line 42, please change “chance” to --change--;

At column 34, line 42, “a drain of the first transistor is connected to the control gate of the first transistor” should be recited before “a drain of the second transistor is connected to a gate of the second transistor”.

Signed and Sealed this

Twenty-sixth Day of October, 2010

A handwritten signature in black ink that reads "David J. Kappos". The signature is written in a cursive, flowing style.

David J. Kappos  
*Director of the United States Patent and Trademark Office*